

Proficiency Certificate

PROJECT TITLE

DIAGNOSIS OF FIVE HYDRANT SYSTEM IN TURKEY

CLIENT

PETROL OFISI

PLACE

International Airport of ANKARA, ANTALYA, BODRUM, DALAMAN, IZMIR

TOTAL AMOUNT

Confidential

DESCRIPTION

Realisation of five hydrant system operative audits in Turkey.

The diagnosis studies initially consisted in collecting and analyzing the essential technical data (plans, flow rates, etc.) from the different sites.


All diagnosis studies have been developed on the technical bases of international El type standards.

The studies carried out by site made it possible to list, via simple diagrams translating the hydraulic models produced, the possible hydrant system design faults.

AFDN advised Petrol Ofisi on the solutions to adopt based on the specific problems highlighted by the studies.

All studies were drafted in English.

Example of a diagram explaining a situation in the Terminal



Low Point

O High Point

Pipe Number 1 Pipe Number 2

V

COMMENCEMENT OF

WORK

END OF WORK

APRIL 2019

DECEMBER 2019

CERTIFICATE

I, the undersigned Yannick ROUFFIGNAC, acting as, Head of Operations - PETROL OFISI, certify that the project described above proceeded in accordance with Industry's state-of-the-art rules and fulfilled the commitments that were set since the original order. I place particular emphasis on the quality of the documentation supplied and the professionalism of this Company that have contributed to the achievement of this project.

In witness whereof, this proficiency certificate is issued to serve the purpose it might be required.

At: Istanbul

Yannick ROUFFIGNAC

Le: 05/05/2020

PETROL OFISI A.Ş.

Ünalan Mah. Libadiye Cad. No:82 F Kat:2-3-4 34700 Üsküdar/İSTANBUL Büyük Mükgilefler V.D. 729 001 5043 Ticaret Sicil No: 456102 www.petrolofisi.com.tr